

Invasive Cardiology Security Website

Interventional - Invasive Cardiology

Product Group: Interventional Invasive Products

Mac-Lab IT/XT/XTi. CardioLab IT/XT/XTi.

Products: SpecialsLab and ComboLab IT/XT/XTi

Recording Systems, Centricity Cardiology

Data Management Systems

Version: 6.9.6 Release 3

Subject: Security Information

Date: 29 June 2018

Summary

The following information is provided to GE Healthcare Technologies customers in regards to known technical security vulnerabilities associated with Mac-Lab® Hemodynamic, CardioLab® Electrophysiology, SpecialsLab and ComboLab IT Recording Systems for Cath Lab, EP Lab and other interventional labs as well as the Centricity® Cardiology Data Management Systems.

Security Patch Base Configuration

The security patch base configuration of the Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi product at release is listed within the MLCL Base Configuration under the Hemodynamic, Electrophysiology and Cardiovascular Information Technologies section of the http://www3.gehealthcare.com/en/Support/Invasive_Cardiology_Product_Security website.

Process

The following actions are taken whenever Microsoft/OEMs releases new security patches:

- The Invasive Cardiology Engineering Team performs a security analysis process for supported Mac-Lab IT/XT/XTi, CardioLab IT/XT/XTi, GE Client Review and INW Server hardware/software.
- If a vulnerability meets Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi validation criteria, the vulnerability is communicated through the GEHC Product Security Database and Invasive Cardiology Security Website within Three weeks of the patch release.

Page 1 of 34 GE Healthcare/29 June 2018



• Upon validation of the Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi vulnerability, the GEHC Product Security Database and Invasive Cardiology Security Website and affected Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi Security Patch Installation Instructions are updated.

The Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi vulnerability validation criteria are as follows: Any vulnerability that allows malware to alter or deny Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi functionality and/or infect and propagate through normal system use.

Customers are responsible to stay informed with Microsoft vulnerability notifications and to visit the Invasive Cardiology websites to understand the Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi impact. Once a security patch is validated, customers are responsible for the installation of security patches. All Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi Security Patch Installation Instructions are available on the Invasive Cardiology Security Website below the Validated Patches table.

Vulnerabilities exposed after the Mac-Lab IT/XT/XTi and CardioLab IT/XT/XTi product release which do not meet the criteria to be validated are not listed within the GEHC Product Security Database and Invasive Cardiology Security Website. These vulnerabilities are deemed to be non-critical and/or outside normal clinical workflow of the Mac-Lab IT/XT/XTi, CardioLab IT/XT/XTi and Centricity INW systems and will not be validated. Unlisted patches should not be installed on the products in order to eliminate malfunction and breakdown risks.



Revision History	4
Installation of the Security Patches on MLCL systems	5
How to Log On to Acquisition and Review Systems	5
How to Log On to the Centricity Cardiology INW Server	6
How to Log On to MLCL Software Only Systems	6
How to Install Printer Firmware	6
How to Update Intel Management Engine Firmware (HP Z440) – HPSBHF03557 Rev. 1	6
Z440 BIOS Update to v2.34 Instructions:	7
Z440 BIOS Update to v2.34 Instructions: ML350 Gen9 BIOS Update to v2.56 Instructions:	3
OPTIONAL – How to Install INW Server Performance Enhancement	3
OPTIONAL - How to Install Plugin 20007 - Disable SSL V2/V3 - KB187498	
OPTIONAL - How to Install Plugin 35291 -Weak Hashing	10
OPTIONAL – How to Install Plugin 65821 –SSL RC4 Cipher Suites Supported	10
OPTIONAL – How Remove Vulnerability for Plugin 63155 – Microsoft Windows Unquoted Service Path Enumeration	11
OPTIONAL – How to Disable the SMB1 Protocol	11
Patch Links	12
6.9.6 Installation Paths	12
MLCL V6.9.6 2017 Patch Updates 1	13
MLCL V6.9.6 2017 Patch Updates 2	
MLCL V6.9.6 2018 Patch Updates 3	19
MLCL V6.9.6 2018 Patch Updates 4	25

Page 3 of 34 GE Healthcare/29 June 2018



MLCL v6.9.6 Optional Security Updates	3
Contact Information	34

Revision History

Revision	Date	Comments
1.0	22 September 2017	 6.9.6 document separation Qualified KB4025341 - July Monthly Rollup Added 6.9.6 Installation paths for simplifying patches installation September Unqualified Patches
2.0	13 October 2017	Added instructions to Disable SMB1 Protocol
3.0	27 October 2017	October Unqualified Patches
4.0	20 November 2017	Added October Qualified Patches
5.0	11 December 2017	November Unqualified Patches
6.0	20 December 2017	For October monthly patch, statement added to uninstall previous monthly patches prior to installation of October monthly patch on the server
7.0	26 January 2018	 Qualified November and December monthly rollups with other patches. Also added January Unqualified patches
8.0	9 March 2018	 Added Unqualified February Patch Qualified minimum password length changes Changed verbiage from "Patch Refresh" to "Patch Updates" Further MLCL System Security Recommendation
9.0	20 April 2018	 Added January, February, March and April Qualified Patches Updated "Further MLCL Systems Security Recommendations" section and moved the section Optional Security Updates
10.0	30 April 2018	 Added "Optionally Remove Abode Reader on INW Server" section to the optional section Added Unqualified April Patch
11.0	17 May 2018	 Added May Qualified Patches Added .NET patches for versions 3.5 SP1, 4.5.2



		Added Microsoft Office Patches
12	29 June 2018	Added Unqualified June Patch

Installation of the Security Patches on MLCL systems

Requirements:

- Updates may be applied at any time other than while the Mac-Lab IT/XT/XTi, CardioLab IT/XT/XTi or SpecialsLab application is open.
- Updates must be re-applied if the system is re-imaged.
- Updates apply to both networked and standalone systems.
- Best practice is to update all applicable MLCL systems at the site.

This document applies to 6.9.6R3 only. Please verify that you are running 6.9.6 using the following procedure before proceeding:

- 1. Launch the Mac-Lab CardioLab application.
- 2. Select Help > About Mac-Lab (or CardioLab, as applicable).
- 3. Verify the version number is **6.9.6 Release 3**.
- 4. Click Close.
- 5. Close the application.

Recommendation: <u>Use Internet Explorer (IE) for Catalog download</u>. If you are using the cart feature to download patches, to see the cart it requires opening another tab or new window for http://catalog.update.microsoft.com

How to Log On to Acquisition and Review Systems

When starting up an Mac-Lab, CardioLab or SpecialsLab Acquisition or Review system, an auto-logon sequence starts and automatically logs on to the operating system. To install a security patch, the user must be logged on as **mlcltechuser**.

NOTE: Password information is contained within the Security Guide Manual. Otherwise, contact the system administrator or GE Technical Support for current password information.

Page 5 of 34 GE Healthcare/29 June 2018



- 1. Power on the Acquisition system.
- 2. The system boots up to the *Custom Shell* screen.
- 3. Press Ctrl + Action + Del.
- 4. Click Logoff. On Windows XP, click Logoff again.
- 5. Click **OK**.
- 6. Immediately hold down the **Shift** key until the login window is displayed.
- 7. Log on to the operating system locally as **mlcltechuser**.
- 8. Log on to the *Custom Shell* locally as micitechuser.

How to Log On to the Centricity Cardiology INW Server

Password information is contained within the Security Guide Manual. Otherwise, contact the system administrator or GE Technical Support for current password information. Logon to the INW Server as **administrator**

How to Log On to MLCL Software Only Systems

Since Software Only systems are supported by the customer, the system needs to be logged into with an **administrator** account.

How to Install Printer Firmware

The system which will apply the firmware to the printer should be provided by the customer.

NOTE: Mac-Lab CardioLab system should not be used to download and/or apply the Printer Firmware.

- Follow the download link in the table
- Select the appropriate printer
- Select English and the applicable MLCL operating system
- Select English and under the Firmware category select the applicable Firmware Update Utility and Click Download
- Launch the firmware installer and follow the instructions to complete the firmware update

How to Update Intel Management Engine Firmware (HP Z440) - HPSBHF03557 Rev. 1

Page 6 of 34 GE Healthcare/29 June 2018



- 1. Logon to the Windows OS and MLCL *Custom Shell* as micitechuser.
- 2. Navigate to the location within the section, MLCL V6.9.6 Patch Updates, which has the Intel Management Engine Firmware Update file sp80050.exe.
- 3. Right-click on the **sp80050.exe** file and select *Run as administrator*.
- 4. Click **Yes** on the User Account Control dialog box.
- 5. Click **Next** on the InstallShield Wizard.
- 6. Accept the agreement and click Next.
- 7. Press Y on the command prompt which states "Do you want to update the Management Engine Firmware now [Y/N]?
- 8. Reboot the system once the firmware update is completed.

Steps to verify the firmware update was successful:

- 1. After system reboots, within the HP screen press **F10** to enter setup menu.
- 2. Go to Main > System Information.
- 3. The ME Firmware Version should be at **9.1.41.3024**.

Z440 BIOS Update to v2.34 Instructions:

1. Go to the HP Customer Support - Software and Driver Downloads website:

https://support.hp.com/us-en/drivers/selfservice/hp-z440-workstation/6978828

- 2. Select BIOS.
- 3. Select *Download* for HP Z440/Z640/Z840 Workstation System BIOS 2.34 Rev.A.
- 4. Log on to the z440 computer as *administrator*.
- 5. Run the downloaded **sp80745.exe** file.
- 6. Select **Yes** to allow.
- 7. Select I accept the terms in the license agreement.
- 8. Select *View Contents of the HPBIOSUPDREC folder*. This opens folder:

C:\\swsetup\SP80745\HPBIOSUPDREC

- 9. Run HPBIOSUPDREC.exe.
- 10. Select **Yes** to allow.
- 11. After several seconds, a log file is created and an install utility window appears. Select *Update* and *Next*.
- 12. Follow the onscreen instructions, select *Restart*.

Page 7 of 34

GE Healthcare/29 June 2018



- 13. The BIOS update will take a few minutes, do not remove power during update. The computer will Reboot twice during this update.
- 14. After the update, on the first boot screen before Windows launches, verify the BIOS version 2.34 on the bottom left of the screen appears.

ML350 Gen9 BIOS Update to v2.56 Instructions:

- Go to the HP Customer Support Software and Driver Downloads website: https://support.hpe.com/hpsc/swd/public/detail?swltemId=MTX_116f29414b06465c96e6bd94ae
- 2. Select **Download** for HP ML350 Gen9 Server BIOS 2.56
- 3. Log on to the ML350 Gen9 Server as *administrator*.
- 4. Run the downloaded cp034882.exe file.
- 5. Click on **Run**
- 6. Click on *Install*
- 7. Follow the onscreen instructions, select *close* after installation is complete.
- 8. Select **Yes** to reboot.
- 9. The BIOS update will take a few minutes, do not remove power during update.
- 10. After the update, on boot screen before Windows launches, verify the BIOS version 2.56 on the bottom left of the screen appears.

OPTIONAL - How to Install INW Server Performance Enhancement

The following patches do not resolve security vulnerabilities and are optional. These patches may improve network performance. The installation procedure below must be followed and all listed patches deployed together. This deployment may take up to 12 hours, the large percentage within the KB2775511 installation.

1. Using a non-MLCL system, visit and download the following patches to removable media.

Visit http://catalog.update.microsoft.com/ and enter the below KB numbers to access the patches.

KB2775511 - http://support.microsoft.com/kb/2775511

KB2732673 - http://support.microsoft.com/kb/2732673

KB2728738 - http://support.microsoft.com/kb/2728738

KB2878378 - http://support.microsoft.com/kb/2878378

The following patches are summarized at KB2473205 - https://support.microsoft.com/en-us/kb/2473205

Page 8 of 34 GE Healthcare/29 June 2018



- KB2535094 http://support.microsoft.com/kb/2535094 Download at https://support.microsoft.com/en-us/hotfix/kbhotfix?kbnum=2535094&kbln=en-us
 KB2914677 http://support.microsoft.com/kb/2914677 Download at https://support.microsoft.com/en-us/hotfix/kbhotfix?kbnum=2914677&kbln=en-us
 KB2831013 http://support.microsoft.com/kb/2831013 Download at https://support.microsoft.com/en-us/hotfix/kbhotfix?kbnum=2831013&kbln=en-us
 KB3000483 http://support.microsoft.com/kb/3000483 Download at http://catalog.update.microsoft.com/
 KB3080140 http://support.microsoft.com/kb/3080140 Download at http://catalog.update.microsoft.com/
 KB3044428 http://support.microsoft.com/kb/3044428 Download at https://support.microsoft.com/en-us/hotfix/kbhotfix?kbnum=3044428&kbln=en-us
- 2. Log on to the INW Server as **Administrator**.
- 3. Insert the removable media and install the patches in the order listed above.
- 4. Follow the Microsoft installation instructions to complete the installation of the patches.
- 5. Select **Windows Start -> Run** and enter **Regedit** and Enter.
- 6. In Regedit window, navigate to HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\services\Tcpip
- 7. In the dialog Menu, select **File -> Export**. Name the file **MLCLRegSave.reg** and place in the **C:\Temp** directory.
- 8. In Regedit windows, from **Tcpip** navigate to **Parameters**.
- 9. In the dialog Menu, select Edit -> New -> DWORD (32-bit) Value. A new entry is created and name it 'MaxUserPort'.
- 10. Right click on 'MaxUserPort', select Modify and enter the value 65534 with a base of Decimal.
- 11. Follow the same procedure above and create a new entry named 'TcpTimedWaitDelay'. Enter the value 60 with a base of Decimal.
- 12. Exit the **Regedit** dialog.
- 13. Reboot the INW Server.

OPTIONAL - How to Install Plugin 20007 - Disable SSL V2/V3 - KB187498

- 1. Log on to Windows as **Administrator** or a member of that group.
- 2. Open a command prompt and enter the following commands:
- 3. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 2.0" /f
- 4. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 2.0\Client" /v DisabledByDefault /t REG_DWORD /d 00000001 /f
- 5. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 2.0\Server" /v DisabledByDefault /t REG_DWORD /d 00000001 /f
- 6. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 2.0\Server" /v Enabled /t REG_DWORD /d 00000000 /f
- 7. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 3.0" /f

Page 9 of 34

GE Healthcare/29 June 2018



- 8. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 3.0\Server" /f
- 9. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 3.0\Server" /v DisabledByDefault /t REG_DWORD /d 00000001 /f
- 10. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Protocols\SSL 3.0\Server" /v Enabled /t REG_DWORD /d 00000000 /f
- 11. Close the command prompt.

OPTIONAL - How to Install Plugin 35291 -Weak Hashing

- 1) Load your security certificate in SOL Server on each ML/CL system in the network (server, acquisitions, reviews and virtual reviews) or the ML/CL standalone acquisition.
- 2) Disable RDP on each member of the network.
 - a) My Computer>Properties>Remote settings>Remote
 - b) Check "Don't allow connections to this computer".
 - c) Click ok and reboot.

OPTIONAL - How to Install Plugin 65821 -SSL RC4 Cipher Suites Supported

- 1. Log on to Windows as **Administrator** or a member of that group.
- 2. Open a command prompt and enter the following commands:
- 3. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Ciphers\RC4 128/128" /f
- 4. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Ciphers\RC4 128/128" /v Enabled /t REG_DWORD /d 00000000 /f
- 5. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Ciphers\RC4 40/128" /f
- 6. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Ciphers\RC4 40/128" /v Enabled /t REG_DWORD /d 00000000 /f
- 8. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\SecurityProviders\SCHANNEL\Ciphers\RC4 56/128" /v Enabled /t REG_DWORD /d 00000000 /f
- 9. Close the command prompt.

Page 10 of 34 GE Healthcare/29 June 2018



OPTIONAL – How Remove Vulnerability for Plugin 63155 – Microsoft Windows Unquoted Service Path Enumeration

- 1. Log on to Windows as Administrator or a member of that group
- 2. Open Regedit do the following
 - a. On Windows 7
 - i. Navigate to HKLM\System\CurrentControlset\Services\RtkAudioService
 - ii. Change the imagepath key value from:

 $\hbox{C:\Program Files\Realtek\Audio\HDA\RtkAudioService.exe}$

To:

"C:\Program Files\Realtek\Audio\HDA\RtkAudioService.exe"

Note: The leading and trailing Quote marks are part of the key value. The quotes are what removes the vulnerability

- b. On Windows 2008R2
 - i. Navigate to HKLM\System\CurrentControlset\Services\Gems Task Scheduler
 - ii. Change the imagepath key value from:

 $\hbox{C:\Program Files (x86)\GE Healthcare\MLCL\Bin\Archive\Utility\GEMS_TaskSvc.exe} \\$

To:

"C:\Program Files (x86)\GE Healthcare\MLCL\Bin\ArchiveUtility\GEMS_TaskSvc.exe"

Note: The leading and trailing Quote marks are part of the key value. The quotes are what removes the vulnerability

OPTIONAL – How to Disable the SMB1 Protocol

- 1. Log on to Windows as **Administrator** or a member of that group.
- 2. Open a command prompt and enter the following commands:
- 3. REG ADD "HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Services\LanmanServer\Parameters" /f
- 4. REG ADD "HKEY LOCAL MACHINE\SYSTEM\CurrentControlSet\Services\LanmanServer\Parameters" /v SMB1 /t REG DWORD /d 00000000 /f
- 5. sc.exe config lanmanworkstation depend= bowser/mrxsmb20/nsi
- 6. sc.exe config mrxsmb10 start= disabled



The patches displayed below are qualified on an independent basis and can be installed on a one-by-one basis, although it is recommended that all qualified patches are installed. There are dependencies within the qualified patch list. In the table below, it is recommended the patches are installed in order from top to bottom to ensure all pre-requisites are met for all patches. On occasion the patch dependencies require system reboots which are identified in the table below.

NOTE: Due to site configurations, system patch set, qualified patches which have been installed previously or patch dependencies, some patches could fail to install due to the functionality is already installed. The Microsoft patch installer will alert you to this issue. It this occurs, please continue with the next patch installation.

Alternate Patch locations: In early 2016 Microsoft announced that some patches would no longer be available on the Microsoft Download Center https://blogs.technet.microsoft.com/msrc/2016/04/29/changes-to-security-update-links/ Therefore, some of the links provided below may not work. Microsoft may move/remove these links at any time without notice. However, if the links do not work, there are two alternate methods for downloading patches. The first is the Microsoft Catalog https://catalog.update.microsoft.com. Most fixes not on Microsoft Download Center will be available from the Microsoft Catalog. If a fix is not available from the Microsoft Catalog, Microsoft has monthly ISO files of the security updates available at https://support.microsoft.com/en-us/kb/913086 To use the ISOs, determine the month of the patch, download the applicable ISO and extract the patch. If after exhausting all three methods, you are still unable to obtain a patch, please contact GE Technical Support for further assistance.

6.9.6 Installation Paths

There are multiple installation paths depending on the version of 6.9.6 installed and any previous patches which have been installed. The following information will help guide you through correct installation path

Determine which version of 6.9.6 you are running. This can be done from the Mac Lab/Cardio Lab application. Go to Help/About and you will see the Release number. The release number combined with the installation scenario will determine the correct path.

Note: The section MLCL Optional Security Updates can be applied after all other patches/updates have been applied. The optional updates provide additional security but are not required. You may apply some of the optional patches but choose to bypass others. For example, you may want to disable some of the vulnerable protocols by you may not want to address Weak Hashing due to cost and complexity of certificate management. This will not cause problems. However, *all other updates are strongly recommended*.

Page 12 of 34 GE Healthcare/29 June 2018



Some updates are documented as <u>superseded</u>. These are left in the document for completeness but can be skipped. The following sample scenarios are provided for reference.

- (1) New Setup/Reimage a machine for disaster recovery.
 - (a) For R3 Apply the updates from the following section
 - (i) MLCL V6.9.6 2017 Patch Updates 1
- (2) The machine was setup and initially patched but no subsequent updates have been applied.
 - (a) For R3 Apply the updates from the following section
 - (i) No further patches are required. The Patch Updates would have been applied as part of setup
- (3) The machine was setup and all previous patches have been applied
 - (a) For R3 Apply the updates from the following section
 - (i) No further patches are required. The Patch Updates would have been applied as part of setup

Unqualified Patches MLCL v6.9.6 R3

	INW Server	Acquisition - Mac-Lab IT/XT/XTi ,	GE Client Review Workstation	Virtual Review
	11444 Server	•	OL Chefft Neview Workstation	VII tudi Neview
		CardioLab IT/XT/XTi and SpecialsLab		
Operating	Windows Server 2008 R2 SP1	Windows 7 SP1	Windows 7 SP1	Windows 7 SP1
System				
Platform				
Current	HPSBHF03576 rev. 1	HPESBHF03805 rev.10	HPESBHF03805 rev.10	HPESBHF03805 rev.10
Unqualified	KB4284867 (CVE-2018-8225)	HPSBHF03576 rev. 1	HPSBHF03576 rev. 1	HPSBHF03576 rev. 1
Vulnerability		KB4284867 (CVE-2018-8225)	KB4284867 (CVE-2018-8225)	KB4284867 (CVE-2018-8225)

MLCL V6.9.6 2017 Patch Updates 1

Windows 7 (Acq	uisition, Review and Virtual Review)	
KB	Link	Notes

Page 13 of 34 GE Healthcare/29 June 2018



	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00023c00	
KB2901907	https://www.microsoft.com/en-us/download/details.aspx?id=42642	Right click and Run as Administrator
Adobe 11.0.20	http://supportdownloads.adobe.com/thankyou.jsp?ftpID=6157&fileID=6191	
KB4025341 July Rollup 2017	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=12c93ad9-ef0e-4ce6-8a1d-84713223d24a	
KB4034664 August Rollup 2017 Superseded	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=e0a94bad-5b2c-4611-9066-24491ce9bb4f	To successfully install this Rollup, you must uninstall July Rollup KB4025341 and reboot before installing KB4034664
Reboot Required	-	
KB4019112	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=1daeb6d1-b103-4baa-bbde-5326e17e89e4	Run KB4014514 and KB4014504 only. For KB4014514, right click and Run as Administrator,
KB3125869	https://support.microsoft.com/en-us/help/3125869/ms15-124-vulnerability-in-internet-explorer-could-lead-to-aslr-bypass-december-16,-2015	Download and install only the "Enable the User32 exception handler hardening feature in Internet Explorer"
KB2889841	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=bb220b30-6d01-4e57-8db6-3e492d6b65d3	-
KB3178688	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=322c28f5-349c-468a-ac94-901616f52372	



http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=06e2c9fb-65b7-48f5-b6e2-58071f17f9bd	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=726adfc6-4ac9-4409-bdab-2892b7058e78	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=6be5e673-e3f6-4c8e-8834-732baf0eb5d3	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=4b4bbe2b-a25d-4509-a069-f5efc227b4ad	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=c8533f11-51f9-4f84-96d8-c619947cc7c0	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=c59a1bb2-ff1f-427a-a8d7-2cab1cb3e7d1	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=f715a81d-102d-416a-9a89-e9ebdace0a6d	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=7698c63a-b85f-4647-bcb1-1be0256c3f43	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=7a599998-ca41-4840-90ea-8143724e5c6a	Use all-proof-en-uscab
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=3658f96e-a521-429d-a9a9-e70e30f5d830	
ftp://ftp.hp.com/pub/softpaq/sp80001-80500/sp80050.exe	Not applicable for Virtual Review.
https://support.hp.com/us-en/drivers/selfservice/hp-z440-workstation/6978828	
http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=ae54ce3d-e321-4831-a1ba-fcae8eb430a0	
	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=6be5e673-e3f6-4c8e-8834-732baf0eb5d3 http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=4b4bbe2b-a25d-4509-a069-f5efc227b4ad http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=c8533f11-51f9-4f84-96d8-c619947cc7c0 http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=c59a1bb2-ff1f-427a-a8d7-2cab1cb3e7d1 http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=f715a81d-102d-416a-9a89-e9ebdace0a6d http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=7698c63a-b85f-4647-bcb1-1be0256c3f43 http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=7a599998-ca41-4840-90ea-8143724e5c6a http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=3658f96e-a521-429d-a9a9-e70e30f5d830 ftp://ftp.hp.com/pub/softpaq/sp80001-80500/sp80050.exe https://support.hp.com/us-en/drivers/selfservice/hp-z440-workstation/6978828



KB4034664 August Rollup 2017		Rollup, you must uninstall July Rollup KB4025341 and reboot before installing KB4034664
Superseded	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=80f7899d-451d-4e3f-b54e-d488a06a3c58	To successfully install this
KB4025341 July Rollup 2017	https://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=b2423c5b-0254-4747-88bb-ec1a785549cb	
KB3125869	https://support.microsoft.com/en-us/help/3125869/ms15-124-vulnerability-in-internet-explorer-could-lead-to-aslr-bypass-december-16,-2015	Download and install only the "Enable the User32 exception handler hardening feature in Internet Explorer"
Adobe 11.0.20	http://supportdownloads.adobe.com/thankyou.jsp?ftpID=6157&fileID=6191	
	State=dword:00023c00	
	Make the following Registry Change [HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
KB	Link Make the fallowing Degistry Change	
Windows 2008R		
	State=dword:00010000	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	Make the Following Registry Change	
Reboot Required	-	



KB4019112	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=dedea6da-e039-487b-8ec6-2729551f7165	Run KB4014514 and KB4014504 only. For KB4014514, right click and Run as Administrator,
HPSBMU03653 rev.1	https://h20566.www2.hpe.com/hpsc/swd/public/detail?swltemId=MTX_083799d6dad34195bb47cb43c1	
Reboot Required		
	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00010000	
	[HKEY_LOCAL_MACHINE\System\CurrentControlSet\Services\NTDS\Parameters]	Apply only on Domain Controller
	LdapEnforceChannelBinding=DWORD:1	Need starting July Rollup- KB4025341 (CVE-2017-8563)

MLCL V6.9.6 2017 Patch Updates 2

The following patches bring the MLCL system to a more recent patch level and address several security vulnerabilities. The following guidelines apply:

- 1) The above patches are required patches for 6.9.6 and must be applied first.
- 2) It is expected that some patches listed will already be on the system.
- 3) Pay attention to the Notes section for special handling instructions
- 4) Patches must be applied in order except where indicated.
- 5) Reboots are only required where indicated. If a Patch requests a reboot at another point, the system can be rebooted but it is not required.
- 6) Patches will not install if the software component to be patched is not present (such as an IE8 patch on a system that does not have IE8 installed).



Note: KB4041681 replaces KB4041678 for both Windows 7 and Windows Server 2008 R2 to address CVE-2017-11771, CVE-2017-11772, CVE-2017-11780, CVE-2017-11781

КВ	Link	Notes
	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00023c00	
	http://supportdownloads.adobe.com/thankyou.jsp?ftpID=6279&fileID=6314	
Adobe 11.0.23		
KB4041681	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=8a346e85-6ae3-46aa-a9e1-	
October 2017	<u>2e70e760f61c</u>	
Monthly Rollup		
	Make the Following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00010000	
	Reboot Required	

Windows 2008R2 (INW Server)

КВ	Link	Notes
	Make the following Registry Change	



	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00023c00	
Adobe 11.0.23	http://supportdownloads.adobe.com/thankyou.jsp?ftpID=6279&fileID=6314	
	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=cd0388fd-5aca-4a13-8417-c28e1d8b7dda	To successfully install this Rollup, you must uninstall July Rollup KB4025341, August Rollup KB4034664 and reboot before applying KB4041681
		Make the following Registry Change – Only on Domain Controller if it does not exist: [HKEY_LOCAL_MACHINE\System\Curre ntContro ISet\Services\NTDS\Parameters] LdapEnforceChannelBinding=DWORD:1
		This registry key is needed on
KB4041681		Domain controller starting July
October 2017		Rollup- KB4025341 (CVE-2017-
Monthly Rollup		8563)
	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00010000	
	Reboot Required	

MLCL V6.9.6 2018 Patch Updates 3

Page 19 of 34 GE Healthcare/29 June 2018



The following patches bring the MLCL system to a more recent patch level and address several security vulnerabilities. The following guidelines apply:

- 1) The above patches are required patches for 6.9.6 and must be applied first.
- 2) Pay attention to the Notes section for special handling instructions
- 3) Patches must be applied in order except where indicated.
- 4) Reboots are only required where indicated. If a Patch requests a reboot at another point, the system can be rebooted but it is not required.

Follow these steps to make the following registry changes to remediate June and September monthly rollup vulnerabilities.

Reference: https://portal.msrc.microsoft.com/en-us/security-quidance/advisory/CVE-2017-8529

Windows 7 (Acquisition, Review and Virtual Review) & Windows 2008R2 (INW Server).

- 1. Click Start, click Run, type regedt32 or type regedit, and then click OK.
- 2. In Registry Editor, locate the following registry folder: HKEY_LOCAL_MACHINE\SOFTWARE\Microsoft\Internet Explorer\Main\FeatureControl\
- 3. Right-click **FeatureControl**, point to **New**, and then click **Key**.
- 4. Type **FEATURE_ENABLE_PRINT_INFO_DISCLOSURE_FIX**, and then press Enter to name the new subkey.
- 5. Right-click FEATURE_ENABLE_PRINT_INFO_DISCLOSURE_FIX, point to New, and then click DWORD Value.
- 6. Type "iexplore.exe" for the new DWORD value.
- 7. Double-click the new DWORD value named iexplore.exe and change the **Value** data field to **1**.
- 8. Click **OK** to close.

Windows 2008R2 (INW Server):

- 1. Click Start, click Run, type regedt32 or type regedit, and then click OK.
- 2. In Registry Editor, locate the following registry folder: HKEY_LOCAL_MACHINE\SOFTWARE\WOW6432Node\Microsoft\Internet Explorer\Main\FeatureControl\
- 3. Right-click **FeatureControl**, point to **New**, and then click **Key**.
- 4. Type FEATURE_ENABLE_PRINT_INFO_DISCLOSURE_FIX, and then press Enter to name the new subkey.
- 5. Right-click FEATURE_ENABLE_PRINT_INFO_DISCLOSURE_FIX, point to New, and then click DWORD Value.
- 6. Type "iexplore.exe" for the new DWORD value.
- 7. Double-click the new DWORD value named iexplore.exe and change the **Value** data field to **1**.
- 8. Click **OK** to close.

Windows 7 (Acquisition, Review and Virtual Review)

Page 20 of 34 GE Healthcare/29 June 2018



КВ	Link	Notes
	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software	
	Publishing]	
	State=dword:00023c00	
KB4048957	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=224b07ab-de98-45f0-8b9c-83551cac66f6	
November 2017		
Monthly Rollup		
	Reboot Required	
KB4054518	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=5b48d1cb-83f7-43e1-9308-18872ffe4dce	
December 2017		
Monthly Rollup		
	Reboot Required	
KB3203468	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=7a599998-ca41-4840-90ea-	
July 2017	<u>8143724e5c6a</u>	
Microsoft		
Office 2010		
KB3213626	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=2bb1487f-b287-41a9-b0ec-	
September	<u>01b42aa4759e</u>	
2017 Microsoft		
Office 2010	http://optology.com/stages/stages/com/stages	
KB3128027	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=474aa90a-7767-4f4f-b3f5-2ffa12fea4e6	
September		
2017 Microsoft		
PowerPoint		
2010	http://optolographicapioneoft.com/s/Joite/Commod/Viscolofficers/2007dateid-02006d7-007d-007d-007d-007d-007d-007d-007d	
KB3141537	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=0c646d3e-697d-4463-a6ea-	
	<u>afb3493c5cea</u>	

Page 21 of 34 GE Healthcare/29 June 2018



Cantambar		
September		
2017 Microsoft		
Publisher 2010		
KB2553338	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=14e73852-cbd2-456a-a9a8-	Might get error message (The
October 2017	7f0c10f1fa40	upgrade path cannot be installed) This error message can be ignored.
Microsoft		This error message can be ignored.
Office 2010 SP2		
KB2837599	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=54ccbc02-879e-4aa1-b817-	
October 2017	12418ce8dfcd	
Microsoft		
Office 2010 SP2		
KB4011612	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=8230d598-8ab1-4efc-89b6-	Might get error message (The
December	<u>d3507a6dfd20</u>	upgrade path cannot be installed)
2017 Microsoft		This error message can be ignored.
Office 2010 SP2		
KB4011660	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=d7594745-04d5-4631-b2d7-	
January 2018	289816f4dd43	
Microsoft Excel		
2010		
KB4011659	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=0b5a1bf0-3043-47fd-afc3-	
January 2018	d2fb55a46a96	
Microsoft		
Word 2010		
KB4011611	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=3b2c376c-ea57-4925-b81d-	Extract to a location and run the
January 2018	3b765d456f2b	extraction to install. Check installed
Microsoft		updates for a successful install.
Office 2010 SP2		
KB4011610	https://www.microsoft.com/en-us/download/details.aspx?id=56447	



http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=537fc3ba-4248-40b8-9498-	Install the following KB4054172,
<u>8a671abebfe9</u>	KB4019990 and KB4054176
Create the following Registry Keys	
Key=[HKEY_LOCAL_MACHINE\SOFTWARE\Microsoft\Windows\CurrentVersion\Policies\Windows\Sidebar\] Value Name=[TurnOffSidebar] Type=[REG_DWORD] Data=[1]	
Create the following Registry Keys	
Key=[HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\Session Manager\] Value Name=[CWDIllegalInDllSearch] Type=[REG_DWORD] Data=[1]	
Make the Following Registry Change	
[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
State=dword:00010000	
Reboot Required	
	Create the following Registry Keys Key=[HKEY_LOCAL_MACHINE\SOFTWARE\Microsoft\Windows\CurrentVersion\Policies\Windows\Sidebar\] Value Name=[TurnOffSidebar] Type=[REG_DWORD] Data=[1] Create the following Registry Keys Key=[HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\Session Manager\] Value Name=[CWDIllegalInDllSearch] Type=[REG_DWORD] Data=[1] Make the Following Registry Change [HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing] State=dword:00010000



Windows 2008R2 (INW Server)

КВ	Link	Notes
	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00023c00	
KB3177467 Service Stack	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=f1b99598-a22d-4fbe-9b63-09724833acc3	Required for successful Monthly rollup installation without uninstalling previous monthly rollup
Service Stack	Deheat Deguised	Tonup
KB4048957 November 2017 Monthly Rollup	Reboot Required http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=435d3006-04ae-4c27-a5f9-3c36f09e58ed	
	Reboot Required	
KB4054518 December 2017 Monthly Rollup	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=09064e30-6f3e-4c99-8d09-fbc2ba06b436	
	Reboot Required	
KB4054172 January 2018 .NET Framework	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=fdecaf44-50a3-4667-a935-f9e7af0bb317	
KB2269637	Create the following Registry Keys	
	Key=[HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Control\Session Manager\] Value Name=[CWDIllegalInDllSearch] Type=[REG_DWORD] Data=[1] Make the Following Registry Change	



[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
State=dword:00010000	
Reboot Required	

MLCL V6.9.6 2018 Patch Updates 4

The following patches bring the MLCL system to a more recent patch level and address several security vulnerabilities. The following guidelines apply:

- 1) The above patches are required patches for 6.9.6 and must be applied first.
- 2) Pay attention to the Notes section for special handling instructions
- 3) Patches must be applied in order except where indicated.
- 4) Reboots are only required where indicated. If a Patch requests a reboot at another point, the system can be rebooted but it is not required.

Windows 7 (Acquisition, Review and Virtual Review)		
КВ	Link	Notes
	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00023c00	
KB4056894 January 2018	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=63bb3909-e5fe-45a2-8d59-44f9df52317f	
Monthly Rollup		
	Reboot Required	



KB4091290	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=c70372c5-bd6c-48f7-b562-c326bc1327a4	
KB4074598 February Monthly Rollup	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=651e95ab- 6e7c-4ea6-9cd2-3cbabd9b76f0	
	Reboot Required	
KB4099950	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=0872a60d-385a-4486-8322-9e759802017a	CAUTION: This patch has to be applied before March Monthly rollup KB4088875. Not applying this before March rollup can affect NIC settings.
KB4088875 March Monthly Rollup	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=3ed75c38-aa36-437e-bf4f-574789591e03	
	Reboot Required	
KB4096040	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=be3cdb55-862c-4362-b015-894e381e07f9	
КВ4099467	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=f325deb3- 28fc-45a3-ab7b-5264f801daf6	
	Reboot Required	
KB4093118 April Monthly Rollup	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=647f49ef-0f0a-49dc-9766-dd255cded1af	
KB4011707	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=969c78ec-cd6a-4295-ade3-a57ca7f8b3b2	
KB3114874	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=9fae99beddc3-4e37-b3ee-9b631fd50eca	



KB3114416	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=da77f81d- 187b-4cae-a75a-d64766a7713d	
KB4057114	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=0aa653a1-1459-44cd-be0b-0fcb77e4ef85	Install AMD64_X86-en-sqlserver2008-kb4057114-x86_a9295f99a2ee7c714f540f3697be0fd4aee7a7bf.exe Run from a cmd prompt as Administrator using the following command: AMD64_X86-en-sqlserver2008-kb4057114-x86_a9295f99a2ee7c714f540f3697be0fd4aee7a7bf.exe /ACTION=Patch /INSTANCENAME=MSSQLSERVER /IGNORESERVICERESTARTSTATE
	Reboot Required	
KB4103718 May 2018 Monthly Rollup	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=3f4d0c73-a177-48cf-a3e7-97d1a94cba87	
	Reboot Required	
KB4095874 .NET 3.5 SP1 and KB4096495 .NET 4.5.2	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=d000d6a2-3321-4381-9a24-3345b2cd0435	KB4099633 is the KB number to use to download and install the patch for KB4095874 and KB4096495. Inside your downloaded file has multiple KBs. Follow these order of installation: 1) Install KB4019990(You may see already installed message for this KB, ignore and continue) 2) KB4095874 3) KB4096495
	Reboot Required	
KB4022146	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=5795d737-4091-4784-a707-007b99d3daef	KB4022146 Microsoft Excel 2010

Page 27 of 34 GE Healthcare/29 June 2018



Microsoft Excel 2010		
KB2899590	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=d8acdbaf-	KB2899590
Microsoft	<u>7f56-4c65-a898-9fdfc7a2d83a</u>	Microsoft Office 2010
Office 2010		
	Make the Following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00010000	
	Reboot Required	

Windows 2008R2 (INW Server)

КВ	Link	Notes
	Make the following Registry Change	
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	
	State=dword:00023c00	
CP034882	https://support.hpe.com/hpsc/swd/public/detail?swltemId=MTX_116f29414b06465c96e6bd94ae	
Firmware		Refer to "ML350 Gen9 BIOS
Update for		Update to v2.56 Instructions"
ML350 Gen 9		section above for installation
Server		instructions
	Reboot Required	
KB4056894	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=fc887fd2-cd35-434b-b6e3-1fef99b2e7ce	



January 2018 Monthly Rollup		
, ,	Reboot Required	
KB4091290	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=c96d43ea-477f-47a1-919f-6936c8d628a3	
KB4074598	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=f3ab18cb-219e-4287-b14c-	
February Monthly Rollup	<u>3a05c8d9479a</u>	
	Reboot Required	
кв4099950	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=38b41383-c716-488c-a937-163bf04f6956	CAUTION: This patch has to be applied before March Monthly rollup KB4088875. Not applying this before March rollup can affect NIC settings.
	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=3af42ab1-13ed-42b5-9e4e-	
KB4096040	<u>a841a71e7f2c</u>	
KB4088875	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=03df6731-e0a6-4917-9da3-	
March	<u>161a0b7f6b09</u>	
Monthly Rollup		
КВ4099467	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=38800bcc-c954-4822-b864-6ae91cc19bb2	
	Reboot Required	
KB4093118	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=d2c7363c-323f-4e92-892a-	
April Monthly Rollup	<u>90b83027e4aa</u>	
	Reboot Required	
	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=0aa653a1-1459-44cd-be0b- 0fcb77e4ef85	Install AMD64-en-sqlserver2008- kb4057114- x64_9ce0b7c5909d8fcc5b9a12d1
KB4057114		7f29b7864a9df33a.exe file. Run

Page 29 of 34 GE Healthcare/29 June 2018



		from a cmd prompt as Administrator using the following command: AMD64-en- sqlserver2008-kb4057114- x64_9ce0b7c5909d8fcc5b9a12d1 7f29b7864a9df33a.exe /ACTION=Patch /INSTANCENAME=MSSQLSERVER /IGNORESERVICERESTARTSTATE
	Reboot Required	
KB4103718 May 2018 Monthly Rollup	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=4fe75106-a2ba-4186-aecd-10424a19225e	
	Reboot Required	
KB4095874 .NET 3.5 SP1 and KB4096495 .NET 4.5.2	http://catalog.update.microsoft.com/v7/site/ScopedViewInline.aspx?updateid=62ccd808-b5a5-4be9-8a38-8e2a829e29d1	KB4099633 is the KB number to use to download and install the patch for KB4095874 and KB4096495. The downloaded file has multiple KBs. Follow these order of installation: 1) Install KB4019990(You may see already installed message for this KB, ignore and continue) 2) KB4095874 3) KB4096495
••••	Make the Following Registry Change	2,
	[HKEY_CURRENT_USER\Software\Microsoft\Windows\CurrentVersion\WinTrust\Trust Providers\Software Publishing]	

Page 30 of 34 GE Healthcare/29 June 2018



State=dword:00010000	
Reboot Required	

MLCL v6.9.6 Optional Security Updates

The following optional updates may be applied to further enhance the security profile of the MLCL systems. These updates should be evaluated on a site-by-site basis in accordance with local IT policy. The configuration changes in this section are compatible with MLCL product functionality but may introduce site specific IT impact as a result of disabling of legacy SSL protocols, prohibiting remote desktop usage and requiring certificate generation and maintenance.

Additional Security Setting and Patches

	INW Server	Acquisition - Mac-Lab IT/XT/XTi , CardioLab IT/XT/XTi and SpecialsLab	GE Client Review Workstation	Virtual Review
Patch	Download URL	Download URL	Download URL	Download URL
MS16-047 KB3149090 Superseded	https://technet.microsoft.com/library/s ecurity/MS16-047	https://technet.microsoft.com/library/s ecurity/MS16-047	https://technet.microsoft.com/library/s ecurity/MS16-047	https://technet.microsoft.com/library/s ecurity/MS16-047
Plugin 20007 – Disable SSL V2/V3 – KB187498	Please see section - How to Install Plugin 20007 - Disable SSL V2/V3 - KB187498	Please see section - How to Install Plugin 20007 - Disable SSL V2/V3 - KB187498	Please see section - How to Install Plugin 20007 - Disable SSL V2/V3 - KB187498	Please see section - How to Install Plugin 20007 - Disable SSL V2/V3 - KB187498
Plugin 78479 - Poodle	No change needed. Step above fixes this.			
Plugin 35291 – Weak Hashing	Please see section - How to Install Plugin 35291 – Weak Hashing	Please see section - How to Install Plugin 35291 – Weak Hashing	Please see section - How to Install Plugin 35291 – Weak Hashing	Please see section - How to Install Plugin 35291 – Weak Hashing
	(Refer to https://technet.microsoft.com/en-us/library/ms191192(v=sql.105).aspx	(Refer to https://technet.microsoft.com/en-us/library/ms191192(v=sql.105).aspx	(Refer to https://technet.microsoft.com/en-us/library/ms191192(v=sql.105).aspx	(Refer to https://technet.microsoft.com/en-us/library/ms191192(v=sql.105).aspx

Page 31 of 34 GE Healthcare/29 June 2018



	INW Server	Acquisition - Mac-Lab IT/XT/XTi , CardioLab IT/XT/XTi and SpecialsLab	GE Client Review Workstation	Virtual Review
	for more information)	for more information)	for more information)	for more information)
Plugin 45411	No change needed. Step above fixes this.	No change needed. Step above fixes this.	No change needed. Step above fixes this.	No change needed. Step above fixes this.
Plugin 65821 – SSL RC4 Cipher Suites Supported (Bar Mitzvah)	Please see section - How to Install Plugin 65821 – SSL RC4 Cipher Suites Supported (Bar Mitzvah)	Please see section - How to Install Plugin 65821 - SSL RC4 Cipher Suites Supported (Bar Mitzvah)	Please see section - How to Install Plugin 65821 - SSL RC4 Cipher Suites Supported (Bar Mitzvah)	Please see section - How to Install Plugin 65821 - SSL RC4 Cipher Suites Supported (Bar Mitzvah)
Plugin 63155 - Microsoft Windows Unquoted Service Path Enumeration	Please see section - How Remove Vulnerability for Plugin 63155 - Microsoft Windows Unquoted Service Path Enumeration	Please see section - How Remove Vulnerability for Plugin 63155 – Microsoft Windows Unquoted Service Path Enumeration	Please see section - How Remove Vulnerability for Plugin 63155 – Microsoft Windows Unquoted Service Path Enumeration	Please see section - How Remove Vulnerability for Plugin 63155 - Microsoft Windows Unquoted Service Path Enumeration
Plugin 59915 – Vulnerabilities in Gadgets Could Allow Remote Code Execution	N/A	Please follow the section titled "Disable the Sidebar in the system Registry" in the following Article: https://technet.microsoft.com/library/security/2719662	Please follow the section titled "Disable the Sidebar in the system Registry" in the following Article: https://technet.microsoft.com/library/security/2719662	Please follow the section titled "Disable the Sidebar in the system Registry" in the following Article: https://technet.microsoft.com/library/security/2719662
Disable SMB1 Protocol	Please see section How to Disable the SMB1 Protocol	Please see section How to Disable the SMB1 Protocol	Please see section How to Disable the SMB1 Protocol	Please see section How to Disable the SMB1 Protocol

Password Policy

Password Policy: Minimum Password Length may be changed above the 14 characters limit to meet security requirements. Refer to **Password** section of the Security Guide for further details about changing passwords.

Optionally Remove Abode Reader on INW Server

Page 32 of 34 GE Healthcare/29 June 2018



We recommend that abode reader be uninstalled on the INW Server. On the server Adobe reader is only used to review INW operator manual. The manual is available in printed format and through online manual portal.

Further MLCL Systems Security Recommendations

We strongly recommend following these recommendations:

- Change default password to stronger, more secure and unique for each user account
- Disable RDP in for each system using the following steps:
 - o My Computer>Properties>Remote settings>Remote
 - o Check "Don't allow connections to this computer".
 - Click ok and reboot.
- If Insite functionality is not used on the system then turn off the VNC service using the following steps:
 - Click on Start button
 - o Click on Control Panel
 - Click on Administrative Tools
 - o Double click Services
 - o Right Click TightVNC Server and select Properties
 - o Under Startup type select Disabled from the dropdown
 - o Click on Apply and Ok

We also recommend following these general recommendations and the recommendations listed in MLCL Security guide

- · Enhanced physical security
- Network firewalls
- Demilitarized Zones and perimeter defenses for site network
- Intrusion detection systems network intrusion protection system
- Virtual Private Networks
- Network traffic analysis
- Log analysis



If you have any additional questions, please contact our Technical Support Department.